

SKF Product Information

Table of correspondence of the complete SKF Driveshaft vs the CV Joint kit (wheel side) to ensure the CV Joint repair



See table below



Compatible SKF CV-Joint kit (Wheel side) in case of repair of the SKF driveshaft



Table of correspondence of the complete SKF Driveshaft vs the CV Joint kit (wheel side) to ensure the CV Joint repair

VKJC XXXX



VKJA XXXX



CAR MAKER	CAR MODELS	VKJC	VKJA
VAG	CORDOBA, IBIZA, INCA, TOLEDO, CADDY, GOLF, JETTA, POLO...	VKJC 1005	VKJA 3021
		VKJC 1012	VKJA 3021
VAG, RENAULT	A3, MEGANE, SCÉNIC, LEON, TOLEDO, OCTAVIA, BORA...	VKJC 1037	VKJA 3011
VAG	A3, TT, LEON, TOLEDO, OCTAVIA, BORA, GOLF, NEW BEETLE	VKJC 1053	VKJA 3011
		VKJC 1054	VKJA 3011
BMW	X5	VKJC 1209	VKJA 5923
BMW		VKJC 1210	VKJA 5923
RENAULT	CLIO, KANGOO	VKJC 1283	VKJA 5354
RENAULT	MEGANE, SCÉNIC	VKJC 1286	VKJA 5981
NISSAN, OPEL, RENAULT	NV400, MOVANO, MASTER	VKJC 1352	VKJA 3040
		VKJC 1353	VKJA 3040
MERCEDES-BENZ	A-CLASS, B-CLASS	VKJC 3297	VKJA 5594
		VKJC 3298	VKJA 5594
		VKJC 3299	VKJA 5594
		VKJC 3301	VKJA 5594
		VKJC 3303	VKJA 5356
PSA, FIAT	JUMPER, DUCATO, BOXER	VKJC 3676	VKJA 3945
		VKJC 3933	VKJA 3945
PSA	BERLINGO, C4, C4 Grand Picasso, C4 Picasso, 3008, 307, 308...	VKJC 4479	VKJA 5345
		VKJC 4507	VKJA 3945
PSA, FIAT	JUMPER, DUCATO, BOXER	VKJC 4508	VKJA 3945
		VKJC 4591	VKJA 3028
VAG	A3, TT, ALTEA, ALTEA XL, LEON, TOLEDO, OCTAVIA, SUPERB, TOURAN...	VKJC 4591	VKJA 3028
VAG, OPEL	A3, Q3, ANTARA, ALHAMBRA, ALTEA, ALTEA XL, LEON, TOLEDO, OCTAVIA, SHARAN, TIGUAN...	VKJC 4592	VKJA 3028
VAG	A3, Q3, ALHAMBRA, ALTEA, ALTEA XL, LEON, TOLEDO, OCTAVIA, SUPERB, CADDY ...	VKJC 4620	VKJA 3028
VAG	A3, ALTEA, ALTEA XL, LEON, TOLEDO, OCTAVIA, SUPERB, CADDY, CC, EOS, GOLF...	VKJC 4621	VKJA 3028
VAG	A4, A6, SUPERB, PASSAT	VKJC 4879	VKJA 3002
VOLVO	S60, V70	VKJC 4937	VKJA 3949
		VKJC 4938	VKJA 3949
PSA	C15, VISA, 205	VKJC 4980	VKJA 5306
VW	MULTIVAN, TRANSPORTER	VKJC 5198	VKJA 5270
		VKJC 5205	VKJA 5270




Table of correspondence of the complete SKF Driveshaft vs the CV Joint kit (wheel side) to ensure the CV Joint repair

CAR MAKER	CAR MODELS	VKJC	VKJA
VAG	A4, SUPERB, PASSAT	VKJC 5444	VKJA 3002
VAG	A4, PASSAT	VKJC 5466	VKJA 3001
VAG	A4, SUPERB, PASSAT	VKJC 5480	VKJA 3005
VAG	A4, EXEO	VKJC 5519	VKJA 3002
VAG	GALAXY, ALHAMBRA, SHARAN	VKJC 7004	VKJA 3007
RENAULT	CLIO, KANGOO, THALIA, TWINGO	VKJC 8102	VKJA 5981
FORD	KUGA	VKJC 8410	VKJA 3970
		VKJC 8416	VKJA 3970
		VKJC 8417	VKJA 3970
		VKJC 8418	VKJA 3970
PSA,FIAT	C5, C6, JUMPY, SCUDO, 407, EXPERT, EXPERT Tepee	VKJC 8523	VKJA 5944
PSA, FIAT	C5, C6, DS5, JUMPY, SCUDO, 407, 508, 508 SW, EXPERT, EXPERT Tepee, RCZ	VKJC 8525	VKJA 5944
OPEL, RENAULT, VAUXHALL	MOVANO, MASTER	VKJC 8533	VKJA 5344
NISSAN	QASHQAI / QASHQAI +2	VKJC 8548	VKJA 5813
		VKJC 8549	VKJA 5813
		VKJC 8635	VKJA 3025
		VKJC 8636	VKJA 3025
PSA,FIAT	JUMPER, DUCATO, BOXER	VKJC 8695	VKJA 3025
		VKJC 8696	VKJA 3025
		VKJC 8697	VKJA 5822
		VKJC 8698	VKJA 5822
		VKJC 8704	VKJA 3024
		VKJC 8705	VKJA 3024

 [Click here to watch SKF technical videos on Youtube](#)

© SKF Group 2021

The contents of this publication are the copyright of the publisher and may not be reproduced (even extracts) unless written permission is granted. Every care has been taken to ensure the accuracy of the information contained in this publication but no liability can be accepted for any loss or damage whether direct, indirect or consequential arising out of the use